

Gym Floor Covers



Complete protective covering systems for your valuable gymnasium floor.

Represented By:



Advantages:

- Protects your gym floor from damage due to improper footwear, tables, chairs, desks or portable staging
- Also protects against burns, spills and dirt
- Reduces the average maintenance costs for your gym floor by up to 45% (**See Page 5**)
- Allows facilities to leverage their resources and use their facility for a variety of activities and events, some of which could easily generate income
- When used with a recommended storage rack, is easy to deploy and remove
- **Manufactured right here in North America**



Material Specifications

Model 55-30 Ultra Heavy-Duty

- 30 oz. per square yard
- Vinyl coated, polyester reinforced fabric
- Fire retardant (meets or exceeds NFPA 701)
- Phthalate free
- Reversible: beige on one side / royal blue on the other
- Recommended usage is over 24 times per year

Model 55-22 Heavy-Duty

- 22 oz. per square yard
- Vinyl coated, polyester reinforced fabric
- Fire retardant (meets or exceeds NFPA 701)
- Phthalate free
- Reversible: gray on one side / royal blue on the other
- Recommended usage is between 10 - 15 times per year

Model SR-8 Storage Rack

- Holds a total of 8 rolls
- Tubular steel, MIG-welded construction
- Finished with powder coated silver vein, chip resistant finish
- Swiveling, non-marring castors
- Furnished with zinc plated hardware and hanger brackets
- Roller bearings are all steel construction
- Features a locking mechanism to prevent unwanted unwinding of material
- Furnished with 2 manual hand cranks
- Rollers feature leader clips

System Accessories

PW-1000 Power Winder

- Dimensions: 17-1/2" L X 3" W X 6-1/2" H
- Weight: 10 lbs.
- Noise emission: 83 Db.
- Motor: 110 V / 1200 W / 50-60 Hz
- Gear head: die cast aluminum housing, permanently greased, variable rotation 35-27 rpm
- Switches: forward and reverse equipped with thermal overload protection and reset button
- Includes attractive storage and carrying case
- 10 year warranty



Makes floor cover removal a breeze!



No more sticky residue!

ST-3 Seam Tape

- Non-residue leaving formula
- Protects against spills
- Keeps overlap seams from being trip hazards
- Comes in cases of 16 rolls
- Rolls are 108' long
- 3" wide

ST-APP Seam Tape Applicator

- Heavy-duty construction
- Large wheel base
- Stable, standalone design
- No bending required



Save your back while quickly taping down your cover!

SR-CVR Storage Rack Cover

- Supplied in 2 pieces with sewn in Velcro strips down the middle for easy attachment
- Constructed of same quality of vinyl as our gym floor covers
- For use where storage is limited or for esthetic reasons
- Comes in a standard color of royal blue
- Custom colors available



Our rack covers keep your system under wraps!

Product Comparisons

Folding Tarps

Advantages

- ✓ Economical
- ✓ Waterproof
- ✓ Rot / mildew resistant
- ✓ Sometimes fire retardant

Disadvantages

- ✗ Folding causes creases which can become both trip hazards and liability issues
- ✗ Folding may cause tears which will compromise it's protective qualities
- ✗ Large sections make handling difficult
- ✗ Weight of large sections require more staff when handling
- ✗ May not lay flat due to lighter weight

Carpeted Sections

Advantages

- ✓ Smaller, easier to handle sections
- ✓ Durable
- ✓ Requires no tools or special equipment to deploy
- ✓ Provides sound absorption
- ✓ Available with a transport cart

Disadvantages

- ✗ Cleaning requires vacuuming, which takes a lot of time
- ✗ Carpet absorbs dust & sand, which can lead to floor damage
- ✗ Sheer amount of sections may take a while to deploy and arrange, not to mention remove
- ✗ Does not protect from spills
- ✗ Costly solution

Vinyl Rolls

Advantages

- ✓ Available in heavier weights
- ✓ Priced very fairly for protection value
- ✓ Easy to manage rolls
- ✓ Waterproof
- ✓ Durable
- ✓ Easily cleaned with a quick dry mop
- ✓ Mildew / rot resistant
- ✓ Available in reversible color combinations
- ✓ Natural weight allows product to lay flatly
- ✓ When used with seam tape will also protect floor from spills
- ✓ Warranties are 5 years and plus
- ✓ Fire retardant

Disadvantages

- ✗ Sections may be fairly heavy when not used with the recommended storage rack



Savings Demonstrations

The following is a demonstration of how a gym floor cover can save your floor and put money in your organization's pocket. These scenarios depict the maintenance* required for a gymnasium hardwood floor over a 20 year period.

Elementary School – Average Gym: 60' wide X 100' long

<u>Scenario A:</u>		<u>Scenario B:</u>	
<ul style="list-style-type: none"> No floor cover is used 2 new hardwood floors are purchased 3 refinishing's are required 19 resealing's are required 1 floor removal (to put in 2nd new floor) 		<ul style="list-style-type: none"> A floor cover is purchased 1 new hardwood floor is purchased 2 refinishing's are required 7 resealing's are required 3 floor cover purchases 	
New Floor Cost	\$168,000	New Floor Cost	\$84,000
Refinishing Cost	\$54,000	Refinishing Cost	\$36,000
Resealing Cost	\$28,500	Resealing Cost	\$10,500
Floor Removal Cost	\$10,800	Floor Removal Cost	\$11,160
Total \$261,300		Total \$141,660	

Total savings over 20 years \$119,640

High School / Post-Secondary – Average Gym: 120' wide X 100' long

<u>Scenario A:</u>		<u>Scenario B:</u>	
<ul style="list-style-type: none"> No floor cover is used 2 new hardwood floors are purchased 3 refinishing's are required 19 resealing's are required 1 floor removal (to put in 2nd new floor) 		<ul style="list-style-type: none"> A floor cover is purchased 1 new hardwood floor is purchased 2 refinishing's are required 7 resealing's are required 3 floor cover purchases 	
New Floor Cost	\$336,000	New Floor Cost	\$168,000
Refinishing Cost	\$108,000	Refinishing Cost	\$72,000
Resealing Cost	\$57,000	Resealing Cost	\$21,000
Floor Removal Cost	\$21,600	Floor Removal Cost	\$22,320
Total \$522,600		Total \$283,320	

Total savings over 20 years \$239,280**

*Maintenance data obtained from several North American school boards

**Does not include savings / incomes that accrue from using buildings a multipurpose venue